


**Date:** December 2016  
**Subject:** CTI Knuckle Options for MFS73 and FL941 - Update  
**Models:** MFS73 AND FL941 Non Drive Front Steer Axle

**Dear Customer**

Meritor® would like to advise an update on the CTI systems that can be installed on the MFS73 AND FL941 steer axles.

Knuckles are available for MFS73 and FL941, to suit the **TIREBOSS™** system from Tire Pressure Control International Ltd (TPC), the **AIR CTI** system and the **Bigfoot** system.

The drilling and tapping of the knuckles for CTI systems is dependent on the particular system, and the appropriate knuckle is required to suit the axle model and brand of CTI being fitted.





Meritor HVS Australia Ltd  
70-76 Berkshire Road  
Sunshine North, Vic Australia

The following knuckle part numbers are available to suit each system;

Axle Model		CTI System	
		TPC and Bigfoot	AIR CTI
<b>MFS73</b>	<b>Left hand knuckle</b>	A-3111-S-19A	A-3111-U-4753
	<b>Right hand knuckle</b>	A-3111-T-20A	A-3111-V-4754
<b>FL941</b>	<b>Left hand knuckle</b>	A-3111-N-4642	A-3111-B-4786
	<b>Right hand knuckle</b>	A-3111-P-4644	A-3111-C-4787

The gross axle weight rating (GAWR) and service guidelines for both axle models are not affected by the use of these new knuckles. Refer to the specific manufacturer for the installation and service requirements of the CTI system.

If you have any questions relating to the above, please contact a Meritor® Australia representative on +613-9300-5200.

**Issued by Product Engineering  
Meritor HVSA Ltd**